

# Village of Barker

---



## **PUBLIC WORKS REPORT** August 2018

Mark Remington, Superintendent  
Gene Cavanaugh  
Robert Verheyen

### **Streets:**

- Mowed roadsides, ditches, garage area and East Ave property and Police building
- Watered plants along Main St., Village Hall and Park
- Trimmed around streets signs and hydrants
- Met with Paul from NC sign shop-ordered street signs, stop signs and children at play sign
- Drove around and checked list of street lights on utility poles
- Installed new street signs at East Ave & High Street
- Took old stop signs down and replaced with new ones-state law says signs have to be reflective to see at night
- Installed children at play sign on Pallister Avenue
- Installed new post and street sign at Quaker Road and Church Street

### **Water:**

- Inspected backflow device at 1693 East Avenue
- Dig request at 8486 West Somerset Road-property was located in the Town of Somerset
- Dig request at 8687 Coleman Road-marked curb box and water service to house
- Dig request at 1726 Quaker Road-located and marked water service and water main
- THM & HAA water samples at 1889 Quaker Road- took to Niagara Falls lab to be tested
- Inspected backflow device at 1872 Pallister Avenue
- 1716 Quaker Road-owner wanted water meter hooked up- house was winterized-installed new water meter because the old meter was badly corroded
- Final water reading at 1706 Quaker Road
- Installed new water meter and outside reader at 1705 Pallister Avenue

### **Equipment:**

- Washed trucks and tractors.
- Cleaned mowing deck and changed blades

### **Parks**

- Mowed and trimmed both parks
- Stained the gazebo on Main Street Village Park
- Called Rich Truesdell for a progress report on the break wall installation project for grant purposes
- Rich Truesdell- near completion on installing the break wall at Bi-Centennial Park

### **Other:**

- Wrote monthly report
- Picked up supplies at Standish & Jones
- Contractors repaired roof on metal building-replaced screws
- Fixed gutter down spout at Village Hall
- Vacation!!
- Shelby Crushed Stone-picked up a load of stone for new water service at Village Hall
- Cut up & removed tree that had fallen down behind metal building at DPW area
- Gordon Fisk-mowing blades and chainsaw chains sharpened